Speech Products Master Upgrade Instructions

Model 5298

Released June 2011

Introduction 1

About the Speech Products Master Upgrade 1
Parts List 1

Requirements and Compatibility 2

System Requirements 2
Compatible Products 2
Incompatible Products 2

Upgrade Scenarios 3

Scenario I – Upgrading Previously Installed Software Versions 3
Scenario II – Upgrading Newly Purchased Products 3
Scenario III – Upgrading Installed KayPENTAX Products in Order to Install New Products 4
Upgrading the Security Key Driver 4
Scenario IV – Upgrading Operating System to Windows 7 or Vista 5
For CSL Model 4500, Sona-Speech, Multi-Speech and PAS prior to 3.2 5
For CSL, Model 4150, and Visi-Pitch IV, Model 3950 prior to 3.2 5
For CSL Model 4500, 4150B, Visi-Pitch Model 3950B and PAS version 3.2 or 3.3 5
For Nasometer II 5



Control No. 7190-5400 Issue G

Introduction

About the Speech Products Master Upgrade

This Speech Products Master Upgrade contains two discs: one titled Speech Products Master Upgrade Service Pack 1, and the other titled Speech Products Master Upgrade Service Pack 2. Depending on the upgrade scenario, you may require one disc or both of the discs. The Speech Products Master Upgrade Service Pack 1 disc is required to upgrade many existing KayPENTAX products on a computer before adding new products. The Speech Products Master Upgrade Service Pack 2 disc is used after a new software installation to install any new features that are not already on your installation discs. Both discs, Service Pack 1 and Service Pack 2, may be needed to upgrade existing products when no new products are being installed.

It is important to follow the instructions for the applicable upgrade scenario to ensure the proper functioning of your KAYPENTAX products.

Parts List

Unpack and inspect the Speech Products Master Upgrade. The following parts should be included:

1. Speech Products Master Upgrade Instructions (this document)
2. Speech Products Master Upgrade Service Pack 1 disc
3. Speech Products Master Upgrade Service Pack 2 disc

If for any reason parts are damaged or missing, immediately contact the factory or a KayPENTAX representative.

Requirements and Compatibility

System Requirements

The Speech Products Master Upgrade requires:

- Current CPU $\geq$ 2 GHz
- Windows 7, Vista, or XP operating system
- Graphics card and monitor that support a minimum screen resolution of 1280x1024
- RAM Requirements: 2 GB for Windows 7, 1 GB for Vista , and 512 MB for XP
- Additional RAM requirements for Voice Games, Model 5167B; Visi-Pitch, Model 3950B; and Sona-Speech, Model 3650
    - 1 GB RAM for Windows XP (or 512 MB RAM and a graphics card with 128 MB memory)
    - 2 GB RAM for Windows Vista (or 1 GB RAM and a graphics card with 128 MB memory)

Compatible Products

This Master Upgrade can be used to upgrade the following products:

- CSL, Models 4500, 4150, 4150B
- Multi-Speech, Model 3700
- CSL/Multi-Speech software options (Models 3506, 4326, 4332, 4333, 4337, 5104, 5105, 5109, 5121, 5127, 5129, 5138, 5141, 5150, 5167, 5167B)
- Visi-Pitch IV, Models 3950, 3950B
- Sona-Speech II, Model 3650
- Phonatory Aerodynamic System, Model 6600
- Nasometer II, Model 6400, 6450

Incompatible Products

The following products cannot be upgraded with this Master Upgrade:

1. KayPENTAX software products version 2.4 or lower CANNOT be upgraded with this Master Upgrade. Before using the Master Upgrade to upgrade existing KayPENTAX software, check the version of your previously installed software (Click the Help menu, and then click About).

2. The following KayPENTAX hardware products CANNOT be upgraded using this Master Upgrade.

    - CSL, Models 4400, 4300, 4300B, 4100
    - Visi-Pitch III, Model 3900; Visi-Pitch II, Model 3300
    - Nasometer, Model 6200

NOTE: Loading new KayPENTAX products onto a computer with existing products that are not upgradeable will render the existing products inoperable.

Upgrade Scenarios

The Master Upgrade is required in each of the following four scenarios to obtain the most up-to-date software features and to ensure proper functioning of the software.

Scenario I – Upgrading Previously Installed Software Versions

If you have an earlier release version of a KayPENTAX program installed on your computer and you wish to update it to take advantage of the most recent software features, perform the following steps:

1. Ensure that the products and versions you have are upgradeable with this Master Upgrade (see **Compatible Products/Incompatible Products**) and that your computer meets the minimum requirements (see **System Requirements**).

2. Check the KayPENTAX software version by opening a software module and selecting Help, About, from the menu bar.

3. If the software version is lower than 3.3, insert the Master Upgrade Service Pack 1 disc into your CD or DVD drive. If the softer is version 3.3 or higher, Service Pack 1 is not required; skip to step 6.

4. The KayPENTAX install screen should automatically appear. Click "Install Master Upgrade" on the main install screen and then "Upgrade" to start the software upgrade.*

5. After the upgrade is complete, a "DONE" button will display on the bottom of the install screen. Click the DONE button to return to the main install screen. Click "Exit" and remove the disc.

6. Insert the Master Upgrade Service Pack 2 disc and follow steps 4 and 5 above.

Scenario II – Upgrading Newly Purchased Products

When installing new KayPENTAX products, run the Master Upgrade after installing your new software to ensure that your program has the most up-to-date features by performing the steps listed below:

NOTE: If you are installing new KayPENTAX products on a computer that already has other KayPENTAX products installed, follow the instructions on the next page.

1. Install the software and hardware of your newly purchased product as detailed in the instruction manual supplied with each KayPENTAX product.

2. After the programs have been installed, insert the Master Upgrade Service Pack 2 disc into your CD or DVD drive. The KayPENTAX install screen should automatically appear. Click "Install Master Upgrade" on the main install screen and then "Upgrade" to start the software upgrade.*

3. After the upgrade is complete, a "DONE" button will display on the bottom of the install screen. Click the DONE button to return to the main install screen. Click "Exit" and remove the disc.

---

*If the install screen does not automatically appear, go to the Windows Start menu, select My Computer (or Computer in Windows 7/Vista), and navigate to the CD or DVD drive. Click on autorun.exe to launch the KayPENTAX install screen. Click "Install Master Upgrade" on the main install screen and then "Upgrade" to start the software upgrade.

Scenario III – Upgrading Installed KayPENTAX Products in Order to Install New Products

To install new KayPENTAX software on a computer that already has earlier KayPENTAX software installed on it, the Master Upgrade is needed to make all software versions compatible prior to installing new KayPENTAX products. Perform the following steps:

1. Ensure that the products and versions you have are upgradeable with this Master Upgrade (see **Compatible Products/Incompatible Products**) and that your computer meets the minimum requirements (see **System Requirements**).

2. Check the KayPENTAX software version by opening a software module and selecting Help, About, from the menu bar.

3. If the software version is lower than 3.3, insert the Master Upgrade Service Pack 1 disc into your CD or DVD drive. If the softer is version 3.3 or higher, Service Pack 1 is not required; skip to step 6.

4. The KayPENTAX install screen should automatically appear. Click "Install Master Upgrade" on the main install screen and then "Upgrade" to start the software upgrade.*

5. After the upgrade is complete, a "DONE" button will display on the bottom of the install screen. Click the DONE button to return to the main install screen. Click "Exit" and remove the disc.

6. Insert the Master Upgrade Service Pack 2 disc and follow steps 4 and 5 above.

7. Install the software and hardware of your newly purchased product as detailed in the instruction manual supplied with each KayPENTAX product.

8. After the programs have been installed, insert the Master Upgrade Service Pack 2 disc again and follow steps 4 and 5 above.

Upgrading the Security Key Driver

You may need to upgrade the security key driver when directed to do so by KayPENTAX technical support. Perform the following steps:

1. Insert the Master Upgrade Service Pack 2 disc into your CD or DVD drive.

2. To upgrade the security key driver, select "Upgrade Security Key Driver" from the main install screen.

3. Follow the prompts in the Aladdin Hasp Device Driver Installation Utility to upgrade the driver.

4. After the upgrade is complete, return to the main install screen. Click "Exit" and remove the disc.

---

*If the install screen does not automatically appear, go to the Windows Start menu, select My Computer (or Computer in Windows 7/Vista), and navigate to the CD or DVD drive. Click on autorun.exe to launch the KayPENTAX install screen. Click "Install Master Upgrade" on the main install screen and then "Upgrade" to start the software upgrade.

Scenario IV – Upgrading Operating System to Windows 7 or Vista

Some previously purchased (prior to version 3.4) KayPENTAX products require new hardware and/or new software installation discs in order to be loaded onto a computer with the Windows 7 or Vista operating system. The following upgrade products are available:

For CSL Model 4500, Sona-Speech, Multi-Speech, and PAS prior to 3.2

To install CSL Model 4500 (and options), Sona-Speech, Multi-Speech, or PAS with software installation discs prior to version 3.2 onto a computer with Windows 7 or Vista, purchase Model 5298 VU, Upgrade – Software Only.

For CSL, Model 4150, and Visi-Pitch IV, Model 3950, prior to 3.2

To install CSL, Model 4150, or Visi-Pitch IV, Model 3950, with software installation discs prior to version 3.2 onto a computer with Windows 7 or Vista, purchase Model 4150 VU, Upgrade for CSL 4150, or Model 3950 VU, Upgrade for Visi-Pitch IV, respectively, which include a replacement audio device (Lynx L22) and software installation discs.

For CSL, Model 4500 and 4150B, Visi-Pitch, Model 3950B, and PAS version 3.2 or 3.3

To install CSL, Model 4500 and 4150B; Visi-Pitch IV, Model 3950B; or PAS, Model 6600, versions 3.2 or 3.3 onto a computer with Windows 7, you will need to use the audio device driver provided in the Master Upgrade Service Pack 2 disc. Perform the following steps:

1. Install the Lynx TWO or L22 audio card as described in the product's Instruction Manual.
2. Insert the Master Upgrade Service Pack 2 disc into your CD or DVD drive.
3. Select "Upgrade Audio Device Driver" from the main install screen.
4. Follow the prompts in the Lynx Device Driver Installation Utility. Return to the main install screen and reboot the computer to complete the installation.
5. Install the software and any software options from your original software installation discs, and then run the Master Upgrade Service Pack 2 (including installation of the security key driver).

For Nasometer II

Nasometer II, Model 6400, cannot be installed onto a computer with Windows 7 or Vista. Nasometer II, Model 6450, is Windows 7 and Vista compatible.

Software version 3.4 or higher is required for installation on a computer with the Windows 7 operating system and can be obtained by running the Master Upgrade Service Pack 2 disc.

Note: VRP, Models 4326-1 and 4326-2, are not transferable to Windows 7 or Vista.



KayPENTAX
A Division of PENTAX Medical Company
3 Paragon Drive
Montvale, NJ 07645-1725 USA

Toll-Free Telephone: 1-800-289-5297 (In USA and Canada only)
Tel: (973) 628-6200
Fax: (201) 391-2063
E-mail: service@kaypentax.com
Web: www.kaypentax.com